

Ship Name: <b>AS-1</b>	Ship Type: <b>Bulk Carrier</b>
IMO Number: <b>8318855</b>	Flag: <b>Turkey</b>
Date of Action: <b>10/03/2005</b>	Class Society: <b>Nippon Kaiji Kyokai</b>
Action Taken: <b>Detention</b>	Recognized Organization: <b>Euroserve Hizmet Ve Isletmecilik</b>
Port: <b>Redwood City, California</b>	Ship Owners, Operators, or Managers: <b>A G Denizcilik Sanayi Ve Ticaret A.S.</b>
	Charterers: <b>Euroserve Hizmet Ve Isletmecilik A.S.</b>
Deficiencies: <u>Code - Category</u> <b>2120 - Garbage</b>	<u>Description</u> <b>Mixed garbage was found throughout ship. Items being burned in the incinerator were not being monitored. The master and crew are not familiar with essential shipboard procedures related to the prevention of pollution by garbage.</b>

Ship Name: <b>CINNA</b>	Ship Type: <b>Bulk Carrier</b>
IMO Number: <b>7433579</b>	Flag: <b>Liberia</b>
Date of Action: <b>10/21/2005</b>	Class Society: <b>Germanischer Lloyd</b>
Action Taken: <b>Detention</b>	Recognized Organization: <b></b>
Port: <b>Staten Island, New York</b>	Ship Owners, Operators, or Managers: <b>Eastmark Associates Inc</b>
	Cinna Shipping Inc.
	Charterers: <b>Phoenix Bulk Corp</b>
Deficiencies: <u>Code - Category</u> <b>0610 - Lifeboats</b>	<u>Description</u> <b>Port lifeboat motor inoperable.</b>
<b>0740 - Pumps</b>	<b>Number one fire pump found inoperable.</b>
<b>2020 - Fire drills</b>	<b>Crew could not perform a satisfactory fire drill.</b>

Ship Name: <b>EAGLE</b>	Ship Type: <b>Bulk Carrier</b>
IMO Number: <b>8126408</b>	Flag: <b>Cyprus</b>
Date of Action: <b>10/07/2005</b>	Class Society: <b>Russian Maritime Register of</b>
Action Taken: <b>Detention</b>	Recognized Organization: <b></b>
Port: <b>Jacksonville, Florida</b>	Ship Owners, Operators, or Managers: <b>Crolier Shipping Limited</b>

Charterers

**Perosea Shipping Co. S.A.**

Deficiencies: Code - Category  
**0220 - Certificates of**

Description  
**Ship is unable to provide for the first watch at the commencement of voyage and for subsequent relieving watches persons who are sufficiently rested and otherwise fit for duty.**

**0220 - Certificates of**

**The Master, Chief Officer, Chief Engineer, Second Engineer and Electrician were intoxicated preparing to get the vessel underway.**

=====

Ship Name: **ENVOY V**

Ship Type: **Tankship (Not Specified)**

IMO Number: **8009246**

Flag: **Panama**

Date of Action: **10/05/2005**

Class Society: **Lloyd's Register of Shipping**

Action Taken: **Detention**

Recognized  
Organization

Port: **Savannah, Georgia**

Ship Owners, Operators, or Managers  
**Envoy Marine Inc.**  
**Val Enterprises S.A. II**

Deficiencies: Code - Category  
**2110 - Oil/oily mixtures  
machinery spaces**

Description  
**Cofferdam in lower engine room filled with a mixture of sewage and heavy black oil.**

**1730 - Oily-water separating  
equipment**

**Vessel crew is unable to test oily water separator. Operator manual for the oily water separator not available onboard.**

=====

Ship Name: **FUNKY**

Ship Type: **Bulk Carrier**

IMO Number: **9057197**

Flag: **Cyprus**

Date of Action: **10/18/2005**

Class Society: **Bureau Veritas**

Action Taken: **Detention**

Recognized  
Organization

Port: **Brunswick, Georgia**

Ship Owners, Operators, or Managers  
**Ice Boss Shipping Company Limited**  
**SPP Maritime SA**

Charterers

**Mid South Feeds Inc**

Deficiencies: Code - Category  
**0720 - Fire fighting equipment**

Description  
**Vessel emergency fire pump is unable to produce firefighting water. Vessel ballasted and operating in a manner rendering the emergency fire pump inoperable.**

Ship Name: <b>HYBUR STAR</b>	Ship Type: <b>General Dry Cargo Ship</b>
IMO Number: <b>5022302</b>	Flag: <b>Panama</b>
Date of Action: <b>10/07/2005</b>	Class Society: <b>Panama Maritime Documentation</b>
Action Taken: <b>Detention</b>	Recognized Organization
Port: <b>Miami, Florida</b>	Ship <u>Owners, Operators, or Managers</u> <b>St. Maarten Reefers Limited</b> <b>Caribbean Marine Management</b>
	<u>Charterers</u> <b>TMM International</b>
Deficiencies: <u>Code - Category</u> <b>0740 - Pumps</b>	<u>Description</u> <b>Main fire pump does not provide sufficient water pressure to effectively fight a fire.</b>
<b>1510 - Navigational equipment</b>	<b>EPIRB not operational and hydrostatic release out of date.</b>
<b>1499 - Other (Prop. &amp; Aux. Machinery)</b>	<b>Rudder Angle indicator is off by 7 degrees.</b>

Ship Name: <b>MSC RIO PLATA</b>	Ship Type: <b>Containership</b>
IMO Number: <b>9122423</b>	Flag: <b>Antigua and Barbuda</b>
Date of Action: <b>10/09/2005</b>	Class Society: <b>Germanischer Lloyd</b>
Action Taken: <b>Detention</b>	Recognized Organization
Port: <b>Staten Island, New York</b>	Ship <u>Owners, Operators, or Managers</u> <b>Northern Vitality</b> <b>Reederei Karl Schluter Gmbh &amp; Co KG</b>
	<u>Charterers</u> <b>Mediterranean Shipping Company (USA) Inc</b>
Deficiencies: <u>Code - Category</u> <b>2510 - Safety and environmental policy</b>	<u>Description</u> <b>Oil discovered in the overboard discharge line of the Oily Water Separator (OWS). Bolted flange just before overboard discharge valve loose and apparent to have been recently detached.</b>

Ship Name: <b>SEABOARD FREEDOM</b>	Ship Type: <b>General Dry Cargo Ship</b>
IMO Number: <b>9141649</b>	Flag: <b>Cyprus</b>
Date of Action: <b>10/15/2005</b>	Class Society: <b>Germanischer Lloyd</b>
Action Taken: <b>Detention</b>	Recognized Organization
Port: <b>Fernandina Beach, Florida</b>	Ship Owners, Operators, or Managers <b>Kommanditgesellschaft Fisser &amp; V. Doornum GMB &amp; Co.</b> <b>Zweiteschiffahrtsgesellschaft Zachariassen</b>
	Charterers <b>Kronoborg Shipping Co Ltd.</b>
Deficiencies: <u>Code - Category</u> <b>1499 - Other (Prop. &amp; Aux. Machinery)</b>	<u>Description</u> <b>Proper operation of the emergency diesel generator could not be demonstrated due to faulty starting control.</b>

Ship Name: <b>THORSEGEN</b>	Ship Type: <b>Bulk Carrier</b>
IMO Number: <b>8116063</b>	Flag: <b>Bahamas</b>
Date of Action: <b>10/11/2005</b>	Class Society: <b>American Bureau of Shipping</b>
Action Taken: <b>Detention</b>	Recognized Organization
Port: <b>San Pedro, California</b>	Ship Owners, Operators, or Managers <b>Norsk Pacific Steamship Co. Ltd</b> <b>Seaspan Ship Managemnt Ltd.</b>
Deficiencies: <u>Code - Category</u> <b>0730 - Appliances (general equipment)</b>	<u>Description</u> <b>Diesel driven emergency fire pump is incapable of delivering adequate pressure and effective stream of water to fight a fire.</b>
<b>1420 - Cleanliness of engine room</b>	<b>Oily rags and leaks throughout engine room presents a fire hazard.</b>